

DATA FORM

MODIFIED ROUTINE ON SITE DETERMINATION METHOD

Field Investigator: See Data Date:
Project/Site: County: State:
Applicant/Owner: Form # Surveyor:
Describe current conditions of wetland and surrounding areas: upland meadow-meadow - just outside tree line.

Has the vegetation, soils, and/or hydrology been significantly disturbed? Yes No X
If yes, what are modifiers:

SOILS

Mapped Series: 44-Ragnar fine sandy loam, 0-6% slopes
Hydric soils list?: Yes No X
Depth Horizon Color Texture Matrix Mottle
0-16" 2.5Y3/3 - sandy loam
Hydric Inclusion?
Hydric Soil Indicators Yes No Depth
Histosol
Histic Epipedon
Gleyed
Sulfidic odor
Concretions

Is the hydric soil criterion met? Yes No X
Rationale: Soil Chroma too high for matrix color.

HYDROLOGY

General wetland type or characteristic: Emergent Scrub/Shrub Forested
Permanently flooded Seasonally flooded Temporarily flooded Saturated
Types of water bodies associated with the wetland: River Stream Seep/Spring
Pond/Lake Tidal Drainage ditch/channel Other:
Is the ground surface inundated? Yes No X Surface water depth:
Is the soil saturated? Yes No X Depth to water in test hole:
Field evidence of surface inundation or soil saturation: NONE

Is the wetland hydrology criterion met? Yes No X
Rationale: No hydrology or evidence of hydrology.

SUMMARY

Hydric soil present? Yes No X Hydrology present? Yes No X
Hydrophytic vegetation present? Yes X No
Percent of FAC, FACW, and OBL species: 75.00%
Is the site a wetland? Yes No X
Rationale: Positive indicators present for only one of the three wetland parameters

TEST HOLE # 4 OF 8

LOCATION OF TEST HOLE Upland north of WB 5

SEE REVERSE FOR VEGETATION



Wiltermood Associates, Inc.
1015 SW Harper Road
Port Orchard, WA 98367
(360) 876-2403